


HALTECH 4 OR 5 BAR MAP SENSORS TERMINATION



LOOKING INTO FRONT OF CONNECTOR

INSERT WIRE THROUGH PLUG, THEN CRIMP THE PIN ONTO THE WIRE
DRAW BACK TO LOCK

Termination	
A	Ground
B	5 Volt
C	Signal