


PRESSURE SENSOR PIN CONNECTIONS



LOOKING INTO FRONT OF CONNECTOR

INSERT WIRE THROUGH PLUG, THEN CRIMP THE PIN ONTO THE WIRE
DRAW BACK TO LOCK